



## [Nortel 920-331](#)

**Exam Name:** Mommunication Server 1000 Ris.5.0 Database Administrator

**Q & A :** 55 Q&As

***Pdf Demo***

### **Quality and Value for the 920-331 Exam**

[Just4Exams Practice Exams](#) for Nortel NCSS 920-331 are written to the highest standards of technical accuracy, using only certified subject matter experts and published authors for development.

### **100% Guarantee to Pass Your 920-331 Exam**

If you do not pass the NCSS 920-331 exam on your first attempt using our Just4Exams **920-331 testing engine and pdf study guide**, we will give you a FULL REFUND of your purchasing fee.

### **Downloadable, Interactive 920-331 Testing engines and PDF Version**

Our Exam Preparation Material provides you everything you will need to take a [NCSS certification](#) examination. Details are researched and produced by [Nortel Certification](#) Experts who are constantly using industry experience to produce precise, and logical.

**Free 920-331 Exams:**

***This is demo only, this pdf do not include the questions and answers picture***

Exam : Nortel 920-331

Title : Mommunication Server 1000 Ris.5.0 Database Administrator

1. Click the Exhibit button.

You have been asked to review and interpret the existing trunk information for your customer.

According to the printout shown in the exhibit, which type of trunk is this?

- A. TIE trunk
- B. digital trunk
- C. virtual trunk
- D. Central Office Trunk

Answer: D

2. Click on the Exhibit button.

A Communication Server (CS) 1000 Rls. 5.0 customer is adding a new accounting department with ten digital telephone users. The customer has asked for the telephones to be programmed with consecutive Directory Numbers (DNs) from their DID range (5000-5399). Which number sequence is available to meet the customers requirements?

- A. 5000 - 5014
- B. 5090 - 5100
- C. 5275 - 5285
- D. 5287 - 5297

Answer: C

3. You have received a customer work order requesting that five new digital telephones be added to the sales department. The customer purchased a new Digital Line Card to support these telephones. Which Overlay (LD) is used to find an unused card slot (LUC) for the new Digital Line Card?

- A. LD 02
- B. LD 20
- C. LD 21
- D. LD 117

Answer: B

4. A customer has a Communication Server (CS) 1000 Rls. 5.0 system. Telephone users are required to use Basic Alternate Route Selection (BARS) to make toll calls. What Class of Service access restriction tells the system to look at the telephone network class of service (NCOS) to determine call eligibility?

- A. FR1
- B. FR2
- C. CTD
- D. UNR

Answer: C

5. A customer requirement is that telephone users have the capability to place a call in a parked state, similar to hold, where it can be retrieved by another set. Which feature, service, or option must be defined within the Customer Data Block (LD 15) before defining the feature for an individual telephone level?

- A. Allow Call Park
- B. Allow Individual Hold
- C. Enable Conference Count Display
- D. Allow Central Office Trunk Priority for Call Pickup

Answer: A

6. A customer has a Communication Server (CS) 1000 Rls. 0 system equipped with System Errors and Events Lookup package 245, which provides the ability to display system messages on screen. When a system message is received, which procedure should they use to look it up and display it on the screen?

- A. Enter the system message followed by <cr>.  
For example, 4080 <cr>
- B. Enter the system error code followed by <cr>.  
For example, bug4080 <cr>
- C. Enter err followed by the system error code and <cr>.  
For example, err bug4080 <cr>
- D. Enter err followed by the system error code and <cr>.  
For example, LOAD errcode bug4080 <cr>

Answer: B

7. The telephones in the Accounting Department have a Class of Service that restricts users from making long distance telephone calls. The customer wants to know if there is a feature that will let personnel in the Accounting Department make long distance calls from an approved list of telephone numbers. Which feature will you activate to meet the customer requirements?

- A. Dial Intercom
- B. System Speed Call
- C. Call Forward by Call Type
- D. Controlled Class of Service

Answer: B

8. A customer has deployed a Communication Server 1000E Rls. 5.0 system at their site. Element Manager is not yet available. When using the Command Line Interface (CLI) to configure the system, you encounter the following system message: OVL0000. What is the

meaning of this system message?

- A. A telephone is disabled.
- B. There is a checksum failure.
- C. A user has already logged into the system.
- D. The requested program is not in the tape directory.

Answer: C

9. A customer has a Communication Server (CS) 1000 Rls. 5.0 system equipped with System Errors and Events Lookup package 245, which provides the ability to display system messages on screen. Which setting should the Multi-User Login feature be set to for the System Lookup Message feature to work?

- A. ON
- B. OFF
- C. LOADED
- D. ENABLED

Answer: A

10. A customer has deployed a Communication Server 1000 Rls. 5.0 system at their site. When using the Command Line Interface (CLI) to add telephones, which Overlays (LDs) are linked to eliminate the need for exiting one Overlay (LD) and entering another one?

- A. LDs 10, 11, 20 and 32
- B. LDs 20, 21, 22 and 32
- C. LDs 14, 15, 16 and 32
- D. LDs 32, 50, 57 and 95

Answer: A

More [920-331 Braindumps](#) Information

#### **Related 920-331 Exams**

|         |         |         |         |         |
|---------|---------|---------|---------|---------|
| 920-803 | 922-097 | 920-250 | 922-096 | 920-322 |
| 922-093 | 922-095 | 920-215 | 920-331 | 920-326 |
| 920-330 | 920-481 | 920-460 | 920-138 | 920-160 |
| 920-118 | 920-172 | 920-251 | 920-233 | 920-249 |

#### **Other Nortel Exams**

|         |         |         |         |         |
|---------|---------|---------|---------|---------|
| 920-209 | 920-160 | 920-021 | 920-325 | 922-060 |
| 922-079 | 920-106 | 920-140 | 920-534 | 920-469 |
| 920-548 | 922-094 | 920-220 | 920-260 | 920-118 |
| 920-105 | 920-807 | 920-505 | 920-460 | 920-183 |