



[EMC E20-611](#)

Exam Name: CLARiiON Installation and Troubleshooting Specialist

Q & A : 142 Q&As

Pdf Demo

Quality and Value for the E20-611 Exam

[Just4Exams Practice Exams](#) for EMC EMC Certification E20-611 are written to the highest standards of technical accuracy, using only certified subject matter experts and published authors for development.

100% Guarantee to Pass Your E20-611 Exam

If you do not pass the EMC Certification E20-611 exam on your first attempt using our Just4Exams **E20-611 testing engine and pdf study guide**, we will give you a FULL REFUND of your purchasing fee.

Downloadable, Interactive E20-611 Testing engines and PDF Version

Our Exam Preparation Material provides you everything you will need to take a [EMC Certification certification](#) examination. Details are researched and produced by [EMC Certification](#) Experts who are constantly using industry experience to produce precise, and logical.

Free E20-611 Exams:

This is demo only, this pdf do not include the questions and answers picture

Exam : EMC E20-611

Title : EMC CLARiiON Installation and Troubleshooting Specialist

1. Which CX4 model supports SATA-II drives as vault drives?

- A. CX4-120
- B. CX4-240
- C. CX4-480
- D. CX4-960

Answer: A

2. How many GB of memory are installed in each CX4-960 SP?

- A. 8

- B. 16
- C. 32
- D. 64

Answer: B

3. It is best practice to place the iSCSI I/O module in the I/O annex first on which CX4 model?

- A. CX4-120
- B. CX4-240
- C. CX4-480
- D. CX4-960

Answer: D

4. Your customer has ordered a CX4-960 configured from the factory for only 480 drives. The customer now wants to upgrade to the 960-drive version of the CLARiiON.

What needs to happen to the CLARiiON to upgrade the CX4-960 to support the full amount of disks?

- A. Need to install a software upgrade only as the I/O devices are already installed
- B. Need to install the new DAE3Ps and disks only; no I/O modules or software required
- C. Need to install the new I/O modules and a software upgrade to get the full supported disk amount
- D. Need to install the new I/O modules only; the software is already installed for the upgrade

Answer: C

5. Which CX4 array model has a maximum number of two BE Fibre Channel ports per storage processor (SP)?

- A. CX4-120
- B. CX4-240
- C. CX4-480
- D. CX4-960

Answer: B

6. A customer has a DAE3P configured and running at 4 Gb/s back-end speed, and you install a 2 Gb/s-only drive in the enclosure.

What will the DAE3P do with the new drive?

- A. It will add the drive at 2 Gb/s back-end speed with no issues and initialize it.
- B. It will add the drive at 4 Gb/s back-end speed with no issues and initialize it.
- C. It will change the back-end speed of the entire enclosure to match the 2 Gb/s drive.
- D. It will not add the drive to the loop due to the incompatible drive speed.

Answer: D

7. Click the Exhibit button.

In which slot is the iSCSI module installed?

- A. 0
- B. 1
- C. 2
- D. 3

Answer: C

8. Which CX4 array model has a maximum number of one back-end Fibre Channel port per storage processor (SP)?

- A. CX4-120
- B. CX4-240
- C. CX4-480
- D. CX4-960

Answer: A

9. What is indicated in a CX4 if the Fault LED on an SP is blinking blue at a frequency of 1 Hz?

- A. FLARE is ready for I/O.
- B. POST is starting the OS.
- C. The FLARE drivers are starting.
- D. The SP is executing POST.

Answer: C

10. How many GB of memory are installed in each CX4-480 SP?

- A. 4
- B. 8

C. 16
D. 32
Answer: B

11. On a CLARiiON CX4-960 array what is the maximum number of drives supported on each back-end loop?

- A. 120
- B. 240
- C. 480
- D. 960

Answer: A

12. Optical cables are required for which connection(s)?

- A. Fibre Channel back-end connections and all iSCSI connections
- B. Fibre Channel back-end connections to disk-array enclosures (DAE)
- C. Fibre Channel front-end host connection to disk-array enclosures (DAE)
- D. Fibre Channel front-end host connection to storage processors (SP)

Answer: D

13. How many BE ports does a CX4-960 array with the expansion option have?

- A. 4
- B. 8
- C. 16
- D. 32

Answer: C

14. Your customer has MirrorView installed and configured on their CX4-480, and they are installing two additional FE UltraFlex I/O modules in the array.

Will the MirrorView ports on the array need to be reconfigured and moved to the highest numbered ports on the new modules?

- A. No. The CLARiiON will automatically move the ports to the highest numbered port on the array.
- B. No. The ports will not need to be reconfigured; the ports will stay the same.
- C. Yes. The ports will need to be auto-assigned by the SPs and moved accordingly.
- D. Yes. The ports will need to be reconfigured in Navisphere Manager to the highest port numbers.

Answer: B

15. How many fans are in a CX4-960 fan pack?

- A. 1
- B. 2
- C. 3
- D. 4

Answer: A

16. How many power supplies/blower modules are needed to start mirrored write caching on a CLARiiON CX4-480?

- A. 1
- B. 2
- C. 3
- D. 4

Answer: C

17. How many UltraFlex I/O module slots are available in a CX4-960 array?

- A. 6
- B. 8
- C. 10
- D. 12

Answer: D

18. On a CLARiiON CX4-480 array what is the maximum number of drives supported on each back-end loop?

- A. 90
- B. 120
- C. 240
- D. 480

Answer: B

19. Click the Exhibit button.

In the illustration, how should the I/O Annex correspond to the SPs from left to right?

- A. SPA, SPA, SPB, SPB
- B. SPA, SPB, SPA, SPB
- C. SPB, SPA, SPB, SPA
- D. SPB, SPB, SPA, SPA

Answer: D

20. How many BE ports does a CX4-480 array have?

- A. 4
- B. 8
- C. 16
- D. 32

Answer: B

More [E20-611 Braindumps](#) Information

Related E20-611 Exams

E20-001	E20-850	E20-120	E20-361	E20-611
E22-211	E20-616	E20-011	E20-351	E22-280
E20-501	E20-455	e20-860	e20-661	E20-405
E20-465	e20-617	E22-201	e20-651	E20-590

Other EMC Exams

e20-845	e20-617	E22-250	E20-515	e20-080
e20-593	E20-331	e20-533	e22-141	e20-822
e20-510	E20-405	e20-060	E20-011	e22-128
e20-532	e20-530	E20-370	e20-570	E20-593