



[CompTIA 220-601](#)

Exam Name: *CompTIA A+ Essentials 220-601 Exam*

Q & A : 214 Q&As

Pdf Demo

Quality and Value for the 220-601 Exam

[Just4Exams Practice Exams](#) for CompTIA A+ 220-601 are written to the highest standards of technical accuracy, using only certified subject matter experts and published authors for development.

100% Guarantee to Pass Your 220-601 Exam

If you do not pass the A+ 220-601 exam on your first attempt using our Just4Exams **220-601 testing engine and pdf study guide**, we will give you a FULL REFUND of your purchasing fee.

Downloadable, Interactive 220-601 Testing engines and PDF Version

Our Exam Preparation Material provides you everything you will need to take a [A+ certification](#) examination. Details are researched and produced by [CompTIA Certification](#) Experts who are constantly using industry experience to produce precise, and logical.

Free 220-601 Exams:

This is demo only, this pdf do not include the questions and answers picture

Exam : CompTIA 220-601

Title : CompTIA A+ Essentials 220-601 Exam

1. A technician opens a computer and observes that the computer is full of dust. Which of the following should the technician do to remove the dust from the system? (Select TWO).

- A. Gently blow the dust out.
- B. Use a dust cloth.
- C. Shake the dust out.
- D. Use compressed air to remove the dust.
- E. Vacuum the dust out of the system.

Answer: DE

2. In Windows 2000/XP, which of the following are valid commands that can be typed into the 'Run' dialog box to access the registry editor? (Select TWO).

- A. REGEDIT
- B. REGEDT32
- C. REGISTRY /EDIT
- D. REG /EDIT
- E. REG32 /EDIT
- F. REGEDIT32

Answer: AB

3. A technician is attempting to run IPCONFIG from the 'Run' dialog box in Windows 2000/XP. After typing in IPCONFIG and selecting OK, a black window briefly appears and disappears. Which of the following describes this situation?

- A. IPCONFIG can only be run in Safe Mode.
- B. IPCONFIG is not a valid Windows 2000/XP command.
- C. IPCONFIG has successfully executed and terminated.
- D. IPCONFIG requires a Terminal Services license.

Answer: C

4. The amount of power output from a power supply is rated in:

- A. volts.
- B. watts.
- C. ampere hours.
- D. joules.

Answer: B

5. NTFS should be used for Windows XP rather than FAT32 because NTFS: (Select TWO).

- A. allows for faster hard drive access.
- B. ensured that all users networked to a computer can read files.
- C. gives a user more useable hard drive space.
- D. allows Windows XP to use all available security features.
- E. ensures full compatibility with new software.

Answer: CD

6. Which of the following describes the function of a chipset on a motherboard?

- A. Transfer data directly from the monitor to the CPU.
- B. Control data transfer to only the hard disk drive.
- C. Allow the computer to determine which operating system to use.
- D. Control the transfer of data to and from the computers peripherals.

Answer: D

7. Which of the following connections are found on video cards? (Select TWO).

- A. RS-232
- B. DB-25
- C. 15-pin D-shell
- D. RJ-45
- E. DVI

Answer: CE

8. Windows XP is being installed from a CD onto a computer that has no operating system. Which of the following installation methods would MOST likely be used?

- A. Multiboot
- B. Network
- C. Attended
- D. Automated

Answer: C

9. Which of the following types of fire extinguishers would be MOST appropriate to use on a fire in a laptop?

- A. Class A
- B. Class B
- C. Class C
- D. Class D

Answer: C

10. A small business customer has a 200-computer network connected with hubs and is reporting that the network is slow. An upgrade using which of the following could be suggested?

- A. Bridges
- B. Switches
- C. Routers
- D. Brouters

Answer: B

11. A technician is updating the video drivers on a Windows XP system and encounters a dialog box warning that the driver is unsigned.

An unsigned driver means that the driver:

- A. is currently in a beta state.
- B. is not signed by the hardware abstraction layer (HAL).
- C. has not been signed by the Windows Hardware Quality Lab.
- D. is incompatible with Windows XP.

Answer: C

12. Which of the following is the fastest method to transfer data wirelessly?

- A. Bluetooth
- B. Standard infrared
- C. General Packet Radio System (GPRS)
- D. 802.11

Answer: D

13. To actively protect end users and maximize efficiency, a technician should configure which of the following in the operating system?

- A. Disk Defragmenter to run every morning at the same time.
- B. System to automatically download and install updates from the Internet.
- C. Disk Cleanup to run every morning at the same time.
- D. Windows Firewall settings to block all Internet traffic.

Answer: B

14. After installing a new cable modem and new router, which of the following should be the order used to start up the devices?

- A. Turn on the cable modem, then the router, and then the computer.
- B. Turn on the cable modem, then the computer, and then the router.
- C. Turn on the router, then the computer, and then the cable modem.
- D. Turn on the computer, then the cable modem, and then the router.

Answer: A

15. Which of the following printer technologies requires heat to adhere the image on the paper?

- A. Laser
- B. Inkjet
- C. Thermal
- D. Impact

Answer: A

16. In Windows XP, which of the following steps would be taken to set the permissions for a user to print within a specific time frame?

- A. Printers and Faxes > right click the printer > Properties > Printer Settings > select the time
- B. Printers and Faxes > right click the printer > Properties > Security tab > Time
- C. Printers and Faxes > right click the printer > Properties > Advanced tab > select the time
- D. Printers and Faxes > right click the printer > Properties > General tab > Time

Answer: C

17. Which of the following assigns IP addresses to computers on a network? (Select TWO).

- A. Exchange Server
- B. Residential Router
- C. DHCP Server
- D. PC assigns its own
- E. Switch

Answer: BC

18. In Windows 2000/XP, which of the following is the filename created by Virtual Memory?

- A. 386PART.PAR
- B. WIN386.SWP
- C. VMM32.VXD
- D. PAGEFILE.SYS

Answer: D

19. IEEE 1284 is a standard for:

- A. infrared communication.
- B. wireless networks.
- C. wired networks.
- D. parallel communication.

Answer: D

20. A technician has installed a new video card and the computer will now only boot into VGA mode. Which of the following may be the cause of the problem?

- A. There is an operating system incompatibility.
- B. The incorrect drivers are installed.
- C. The external monitor is not compatible.
- D. The new card is not DVI compatible.

Answer: B

More [220-601 Braindumps](#) Information

Related 220-601 Exams

220-602	220-701	220-601	220-702	220-603
220-303	220-604	220-302	220-301	220-304
BR0-003	JK0-601	220-611	JK0-602	JK0-701
220-612				

Other CompTIA Exams

JK0-702	n10-003	pk0-002	TK0-201	RF0-001
PD0-001	JK0-009	220-702	JK0-010	TK0-202
220-602	FC0-U21	TK0-203	SY0-201	220-603
TK0-250	JK0-U31	JK0-601	JK0-011	JK0-701