



[Nortel 920-448](#)

Exam Name: nncse-alteon security

Q & A : 47 Q&As

Pdf Demo

Quality and Value for the 920-448 Exam

[Just4Exams Practice Exams](#) for Nortel NCSE 920-448 are written to the highest standards of technical accuracy, using only certified subject matter experts and published authors for development.

100% Guarantee to Pass Your 920-448 Exam

If you do not pass the NCSE 920-448 exam on your first attempt using our Just4Exams **920-448 testing engine and pdf study guide**, we will give you a FULL REFUND of your purchasing fee.

Downloadable, Interactive 920-448 Testing engines and PDF Version

Our Exam Preparation Material provides you everything you will need to take a [NCSE certification](#) examination. Details are researched and produced by [Nortel Certification](#) Experts who are constantly using industry experience to produce precise, and logical.

Free 920-448 Exams:

This is demo only, this pdf do not include the questions and answers picture

Exam : Nortel 920-448

Title : NNCSE-Alteon Security

Version : Demo

1. A support engineer wants to monitor real time sessions going through a firewall. Which command will accomplish this task?

- A. cp fw mon
- B. FW monitor
- C. /i/fw/session
- D. via the log viewer

Answer: B

2. Which command describes how to configure RIP Routing?

- A. /cfg/route/rip
- B. /cfg/net/route/rip
- C. /cfg/route/rip1 or rip2
- D. /cfg/net/route/rip1 or rip2

Answer: B

3. An ASF cluster has the following configuration: ? multiple firewall directors ? accelerator components to be updated and configured as a whole This is know as what type of configuration?

- A. NAAP
- B. Clustering
- C. Management IP Address
- D. Single System Image (SSI)

Answer: D

4. By default on the ASF 5000 series platform, which port or ports are set to use the NAAP protocol?

- A. Port 9
- B. Ports 1-5
- C. Ports 6,7, and 8
- D. Ports 5,6,7,and 9

Answer: C

5. In order to achieve stateful fail-over between an ASF cluster, where must synchronization be configured?(Choose two.)

- A. the Alteon Accelerator
- B. the Alteon Switched Firewall
- C. the Checkpoint SMART TRACKER
- D. the Check Point management server

Answer: BD

6. A support engineer wants to add multiple devices to a cluster. How can they verify that the MAC address of the secondary ASF has been detected by the master ASF?

- A. /cfg/d
- B. /info/net
- C. /i/fw/cluster
- D. /cfg/acc/cur

Answer: D

7. A support engineer upgraded an ASF network from 2.0 to 3.0 using the .pkg file and noticed problems within the existing OSPF network. What is the most likely cause of the problem?

- A. The ARP Cache has filled up.
- B. The routing table has maxed out inadvertently.
- C. Upgrading from 2.0 to 3.0 does not support an OSPF upgrade.
- D. OSPF neighbors have lost communication with the ASF running OSPF.

Answer: C

8. What is the proper way to install a Central Checkpoint License?

- A. /cfg/pnp/add
- B. /cfg/fw/license
- C. via Secure update
- D. /maint/fw/license

Answer: C

9. A support engineer is tasked to troubleshoot a network consisting of an ASF 5010 Cluster of two SFD's and two SFA's with 2.0 software running sync on Ethernet 2 between the two SFD's. The support engineer types in the ?info/clu?command and notices synch errors. What can be concluded about the synch error messages? (Choose two.)

- A. SFD lost communication with SFA.
- B. Policy has not been pushed to cluster.
- C. The two SFD's lost communication with their GW.
- D. One of the SFD's sync ports has been unplugged.
- E. No valid checkpoint license has been installed onto the cluster.

Answer: BD

10. A support engineer is logged into an ASF via the Command line interface (CLI). Which command would the engineer issue to see the current Check Point Firewall versions that are installed?

- A. /cfg/dump
- B. /info/fw/cur
- C. /cfg/software/cur
- D. /cfg/fw/software/cur

Answer: D

More [920-448 Braindumps](#) Information

Related 920-448 Exams

920-453	920-448	920-804	920-447	920-441
920-458	920-452	920-468	920-443	920-449

Other Nortel Exams

922-072	920-328	920-252	920-255	920-520
920-138	920-324	920-226	922-099	922-100
920-146	920-504	920-221	920-521	920-246
920-362	920-465	922-096	920-257	920-434